## - Site Report -

Date: December 12 2008

IRD Sales Order: 11013

To: Greg Felsing
From: Bryan Knight
Project Name/Location: SPS55 / NM I10E mp 50
Service Date(s): December 12 2008

Job Description: Performed Annual System Health Check.

Work Completed: Measured and Recorded the Inductance, Resistance, and Voltage readings of the inroad sensors (Kistler and Loops). Measured Solar Panel Output and MODEM supply voltage. No discrepancies noted. System is fully functional.

Work Remaining: None

Schedule Include Estimate to Complete (on-track, ahead, behind): N/A

Parts Used: None

Pre-mature Equipment Failure: None Noted

Mileage / Travel Time: Total Travel 4 hrs. Total Onsite 4 hrs.

**Safety Concerns: None Noted** 

**Issues Related to Sub-Contractors:** 

Other Notes:





## **Action Items:**

Item	Action Required	Ownership
1.		
2.		
3.		
4.		